

Document Number	FSB 001
Revision	REV A
Application	Public
Effective Date	2022-04-01
Expiry Date	N/A

Field Service Bulletin

Bulletin Type		Severity Recommendation	
<input type="checkbox"/>	Warranty Service	<input type="checkbox"/>	High – Perform immediately
<input checked="" type="checkbox"/>	Informational	<input type="checkbox"/>	Medium – Perform at next scheduled Maintenance
<input type="checkbox"/>	Customer Specific	<input checked="" type="checkbox"/>	Low – Perform whenever system exhibits symptoms

Subject: GPS Sync upgrade

Model / System Affected: GPS Sync

The GPS Sync has undergone a number of upgrades to make the unit easier to read and the addition of a buzzer.

- New TFT colour display
 - Higher quality display
 - More legible font
- Optional trigger buzzer
 - Connects in line with trigger cable
 - Issues a “beep” each time the GPS Sync is triggered
 - Available on serial numbers 1036 and higher

Further Support	https://verif-i.com/contact/
-----------------	-------------------------------------------------------------------------